

**UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION**Page 1 of 1

PATENT NO. : 6,943,744  
APPLICATION NO.: 10/616,017  
ISSUE DATE : September 13, 2005  
INVENTOR(S) : Vezmar

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the drawings, Sheet 2, FIG. 3, the reference numeral 39 applied to the end wall at the open end of the main port 16 adjacent to the low noise block converter 24 should be deleted, and it should be replaced with the reference number 37; and

Column 3, line 62, please delete "39" and insert - -37- -.

**MAILING ADDRESS OF SENDER (Please do not use customer number below):**

**YOUNG & BASILE, P.C.**  
Todd L. Moore  
3001 West Big Beaver Rd., Ste. 624  
Troy, Michigan 48084-3107

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

SEP 29 2005